



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250507154715
Test Time: 2025-05-07 15:47:15
Technician: Andrick

Mitsubishi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mitsubishi/ASX/--
VIN: JMYXTGA2WFZC00803

Odometer Reading: 170681
License Plate: KZ53RWGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System		Status/DTC
MPI/GDI/Diesel		✓ 0
AT/CVT/A-MT/TC-SST		✓ 0
ABS/ASC/ASTC/WSS - A.S.C.		✓ 0
SRS-Air Bag		✓ 0
Meter		✓ 0
Air Conditioner		✓ 0
Auto Cruise	ADAS	✓ 0
4WS/Electric Power Steering		✓ 0
Steering Angle Sensor		✓ 0
KOS/IMMO/Keyless/TPMS - IMMOBI & KOS		✗ 1
AFS/ACL/Leveling	ADAS	✓ 0
OSS		✓ 0
Corner Sensor/Back Sensor		✓ 0
ETACS - Selection 102		✓ 0
LIN - Selection 102		✗ 1

DTC (2)

KOS/IMMO/Keyless/TPMS - IMMOBI & KOS (1 DTC)

DTC	Description	Status
B1A10	Keyless/KOS key 1 low battery	Active DTC

LIN - Selection 102 (1 DTC)



DTC	Description	Status
L0432	RLS RS adaptation error	Stored DTC

Technician Notes
2016869007

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.