

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Starlet cross/--
VIN: JTDLWFA3S00284814

Odometer Reading: 48109
License Plate: LCN438NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
TCM(Transmission Control Module)	 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 4
SRS(Airbag)	 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 2
CGW(Central gateway control module)	 1
EPS(Power steering)	 0
BCM(Body Control Module)	 3
LTS(Lighting and turn signal)	 1
ADM(360 view camera)	  6
HUD(Head-up display)	  0

DTC (17)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (4 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U0401-81	CAN invalid data from ECM	History
U0402-81	CAN invalid data from Transmission Control Module (TCM)	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

U0121-87	Lost communication with ABS or electronic stability program control module	History
U0401-81	CAN invalid data from ECM	History

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0121-87	Lost communication with ABS or electronic stability program control module	History

BCM(Body Control Module) (3 DTCs)

DTC	Description	Status
B140B-00	Remote controller battery low	History
U0121-87	Lost communication with ABS or electronic stability program control module	History
U0401-81	Invalid Data Received from ECM	History

LTS(Lighting and turn signal) (1 DTC)

DTC	Description	Status
U0121	Lost communication with ABS or electronic stability program control module	History

ADM(360 view camera) (6 DTCs)

DTC	Description	Status
B1D01-00	Front camera signal fault	History
B1D02-00	Rear camera signal fault	History
B1D03-00	Left camera signal fault	History
B1D04-00	Right camera signal fault	History
U0121-87	Lost communication with ABS or electronic stability program control module	History
U0401-81	CAN invalid data from ECM	History

Technician Notes
2017295712

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.