



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250509120115
Test Time: 2025-05-09 12:01:15
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla sport/--
VIN: JTNKY3BE403002338

Odometer Reading: 64974km
License Plate: JZ38RNGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine	 1
Transmission	 0
Combination meter	 3
Brake/EPB	 2
Master switch	 0
EMPS	 1

DTC (7)

Engine (1 DTC)

DTC	Description	Status
P160400	Startability fault	Confirmed/TestFailed/Pending

Combination meter (3 DTCs)

DTC	Description	Status
U012987	Lost communication with brake system control module missing message	Confirmed
U016387	Lost communication with navigation control module missing message	Confirmed
U110687	Lost communication with electric parking brake module missing message	Confirmed

Brake/EPB (2 DTCs)

DTC	Description	Status
-----	-------------	--------



C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed
C14FE14	Steering angle sensor supply voltage circuit short to ground or open	Confirmed

EMPS (1 DTC)

DTC	Description	Status
U012987	Lost communication with brake system control module missing message	Confirmed

Technician Notes
2016871779

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.