

JAC VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/JAC/JAC pick-up truck/T8 Pro/--
VIN: LJ11PABE4RC084250

Odometer Reading: 56394km
License Plate: HGY189L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V8.51

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (19)

System	Status/DTC
EMS (Engine System)-EMS (Engine Management System) (2.0CTI)	 1
ESP (Electronic Parking System)	 4
SRS (Supplementary Restraint System)	 0
ICM (Instrument Panel System)-ICM (Instrument Panel System)	 1
APM (Window Anti-pitch System)	 5
BCM (Body Control System)-BCM (Body Control System)	 1
ESCL (Electronic Steering Column Lock)	 2
HVAC (Automatic Air-conditioning System)-HVAC (Heating, Ventilation and Air Conditioning)	 1
MP5 (Media Player System)-MP5 (Media Player System)	 1
PDC (Park Pilot System)	  1
WLC (Wireless Charging)	 1
EPS (Power Steering System)	 0
GSM (Gear Selector Module)	 0
TCU (Transmission Control Unit)	 2
MP5 (Media Player System)	 1
HVAC (Automatic Air-conditioning System)	 1
BCM (Body Control System)	 1

ICM (Instrument Panel System)

 1

EMS (Engine System)

 1 **DTC (25)****EMS (Engine System)-EMS (Engine Management System) (2.0CTI) (1 DTC)**

DTC	Description	Status
P229964	Accelerator pedal and brake pedal signal implausible	History DTCs

ESP (Electronic Parking System) (4 DTCs)

DTC	Description	Status
C003408	Right front Wheel Speed Sensor (WSS): signal out of range, lost, noise, intermittent	Current DTCs
C003408	Right front Wheel Speed Sensor (WSS): signal out of range, lost, noise, intermittent	History DTCs
C006B06	ABS/electronic stability program control abnormal (control time too long, etc.)	History DTCs
U000700	CAN bus undervoltage	History DTCs

ICM (Instrument Panel System)-ICM (Instrument Panel System) (1 DTC)

DTC	Description	Status
U018787	Lost communication with MP5	History DTCs

APM (Window Anti-pitch System) (5 DTCs)

DTC	Description	Status
B100216	Battery voltage too low	History DTCs
B231200	Left rear door motor output current too small	History DTCs
B231100	Right front door motor output current too small	History DTCs
U014087	Lost communication with BCM	History DTCs
B231000	Left front door motor output current too small	History DTCs

BCM (Body Control System)-BCM (Body Control System) (1 DTC)

DTC	Description	Status
B150900	Brake signal abnormal	History DTCs

ESCL (Electronic Steering Column Lock) (2 DTCs)

DTC	Description	Status
B120564	Drive door hardwire signal inconsistent with bus signal	Current DTCs
B120564	Drive door hardwire signal inconsistent with bus signal	History DTCs

HVAC (Automatic Air-conditioning System)-HVAC (Heating, Ventilation and Air Conditioning) (1 DTC)

DTC	Description	Status
U018787	Lost communication with MP5	History DTCs

MP5 (Media Player System)-MP5 (Media Player System) (1 DTC)

DTC	Description	Status
U026787	Wireless Charging Module (WLC) controller communication timeout	History DTCs

PDC (Park Pilot System) (1 DTC)

DTC	Description	Status
U014187	Lost communication with MP5	History DTCs

WLC (Wireless Charging) (1 DTC)

DTC	Description	Status
U018687	MP5 communication timeout	History DTCs

TCU (Transmission Control Unit) (2 DTCs)

DTC	Description	Status
U04165A	Wheel speed signal failure	Current DTCs
U04165A	Wheel speed signal failure	History DTCs

MP5 (Media Player System) (1 DTC)

DTC	Description	Status
U026787	Wireless Charging Module (WLC) controller communication timeout	History DTCs

HVAC (Automatic Air-conditioning System) (1 DTC)

DTC	Description	Status
U018787	Lost communication with MP5	History DTCs

BCM (Body Control System) (1 DTC)

DTC	Description	Status
B150900	Brake signal abnormal	History DTCs

ICM (Instrument Panel System) (1 DTC)

DTC	Description	Status
U018787	Lost communication with MP5	History DTCs

EMS (Engine System) (1 DTC)

DTC	Description	Status
P229964	Accelerator pedal and brake pedal signal implausible	History DTCs

Technician Notes

2017296814

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.