

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00500122657

Odometer Reading: 11134
License Plate: MJ34ZRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
INJ(Injection)	 6
ABS(Anti-lock braking system)	 6
ABG(Airbag / pretensioners)	 3
TDB(Instrument panel)	 1
UCH(Central control unit)	 8
UCC(Communications unit)	  0
DAV(Variable power assist steering)	 6
GW2(Central gateway)	 0

DTC (30)

INJ(Injection) (6 DTCs)

DTC	Description	Status
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Active
DTCC12187	Multiplexed traction control connection Missing message	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (6 DTCs)

DTC	Description	Status
DTC402004	Pump motor control circuit Pump fault	Memory
DTC40201C	Pump motor circuit Feed voltage too high	Memory
DTC505004	Computer ECU fault.	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory
DTCC40100	Invalid INJ. Multiplex signals ABS multiplex invalid signals	Memory
DTCF00317	Computer supply voltage too high Circuit voltage above threshold	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D224	Warning light circuit fault Signal high	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (8 DTCs)

DTC	Description	Status
DTC5A8055	Tire pressure monitor function Not configured	Active
DTC5A8268	Wheel valve sensor 1 Event signal	Memory
DTC5A8368	Wheel valve sensor 2 Event signal	Memory
DTC5A8468	Wheel valve sensor 3 Event signal	Memory
DTC5A8568	Wheel valve sensor 4 Event signal	Memory

DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC956024	Start of clutch switch travel circuit General signal failure	Memory
DTC956123	End of clutch switch travel circuit	Memory

DAV(Variable power assist steering) (6 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560117	Computer power supply Battery voltage too high	Memory
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

Technician Notes
2017298444

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.