



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240611102718
Test Time: 2024-06-11 10:27:18
Technician: Sbu

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00600103468

Odometer Reading: 319
License Plate: LP32DMGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
Injection	 3
ABS	 0
Airbag / pretensioners	 0
Instrument panel	 0
UCH	 0
Communications unit	  0
Variable PAS	 0
Central gateway	 0
Hands-free module	 0

DTC (3)

Injection (3 DTCs)

DTC	Description	Status
DTC073696	Gear r speed coherence Mechanical failures	Memory
DTC091112	Gear selector motor circuit Short-circuit to +12V	Memory
DTC091512	Gear engagement actuator Short-circuit to +12V	Memory



Technician Notes

2016413511

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.