



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250210151317
Test Time: 2025-02-10 15:13:17
Technician: Andrick

Audi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Audi/Audi Q7/SQ7 USA/CAN 2007>/--
VIN: WAUZZZ4L9ED005894

Odometer Reading: 275548
License Plate: FP35SJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(27)

System	Status/DTC
01 - Engine Control Module 1	 9
02 - Transmission electronics	 3
03 - Brakes 1	 3
05 - Access/start authorization	 2
08 - Air Conditioning	 4
09 - Electronic central electric	 2
0E - Media Player Position 1	 2
10 - Parallel parking 2	 1
15 - Airbag	 1
16 - Steering column electronics	 2
17 - Instrument cluster	 4
18 - Auxiliary/parking heating	 3
19 - Gateway	 3
36 - Seat adjustment, driver side	 1
42 - Driver's door electronics	 2
46 - Comfort System Central Control Module	 7
4C - Tire Pressure Monitoring 2	 4
52 - Passenger's door electronics	 2
55 - Headlight Regulation	 1



56 - Radio		1
5F - Information electronics 1		1
62 - Left rear door electronics		1
69 - Trailer Function		2
6C - Camera System Rear View		 2
6D - Rear lid electronics		0
6F - Comfort System Central Control Module 2		0
72 - Right rear door electronics		1

**DTC (64)****01 - Engine Control Module 1 (9 DTCs)**

DTC	Description	Status
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P057100	Cruise/brake switch A circuit Fault	Passive/Sporadic
P067500	Cylinder 5 Glow Plug Circuit	Active/static
P013300	O2 Sensor Circ.,Bank1-Sensor1 Slow Response	Active/static
P241400	Bank1 Sensor1 Voltage too low/air leak	Passive/Sporadic
P219600	O2 Sensor Signal Stuck Rich Bank 1 Sensor 1	Active/static
P162400	Requirement - malfunction lamp on active	Active/static
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static
U140A00	Terminal 30 Open circuit	Active/static

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U012100	Lost Communication With Anti-Lock Brake System (ABS) Control Module	Passive/Sporadic
U021200	Lost communication with steering column control unit	Passive/Sporadic

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
-----	-------------	--------

01314:004	Engine control unit - No signal/communication	Passive/Sporadic
00668:001	Vehicle voltage terminal 30 - Upper limit exceeded	Passive/Sporadic
01826:000	Steering angle sensor, voltage supply terminal 30	Active/static

05 - Access/start authorization (2 DTCs)

DTC	Description	Status
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

08 - Air Conditioning (4 DTCs)

DTC	Description	Status
00003:003	Control module - mechanical malfunction	Passive/Sporadic
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
00446:000	Function limitation due to insufficient voltage	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
01496:010	Left fog light bulb - Open circuit/short circuit to B+	Active/static
00979:010	Right low beam headlamp bulb - Open circuit/short circuit to B+	Active/static

0E - Media Player Position 1 (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

10 - Parallel parking 2 (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
02095:000	Component protection active	Passive/Sporadic

16 - Steering column electronics (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01426:004	Control unit in steering wheel - No signal/communication	Passive/Sporadic

17 - Instrument cluster (4 DTCs)

DTC	Description	Status
00003:005	Control module - no or incorrect basic setting/adaptation	Active/static
01321:004	Airbag control module - No signal/communication	Passive/Sporadic
01316:004	Brake control module - No signal/communication	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

18 - Auxiliary/parking heating (3 DTCs)

DTC	Description	Status
01444:000	Low voltage cut-out (automatic)	Passive/Sporadic
00664:002	Fuel gauge - Lower limit not reached	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
03041:000	Energy management active	Passive/Sporadic
02103:004	Veh. elec. sys. ctrl. mod. 2 - No signal/communication	Active/static

36 - Seat adjustment, driver side (1 DTC)

DTC	Description	Status
01299:004	Diagnostic interface for data bus - No signal/communication	Passive/Sporadic

42 - Driver's door electronics (2 DTCs)

DTC	Description	Status
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
00446:000	Function limitation due to insufficient voltage	Passive/Sporadic

46 - Comfort System Central Control Module (7 DTCs)

DTC	Description	Status
01403:011	Rear glass breakage sensors - Open circuit	Active/static
02103:004	Veh. elec. sys. ctrl. mod. 2 - No signal/communication	Active/static
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
02103:013	Veh. elec. sys. ctrl. mod. 2 - Please read DTC	Passive/Sporadic
01134:004	Alarm horn - No signal/communication	Passive/Sporadic
01503:009	Bulb for high-mount brake light - Open circuit/short circuit to ground	Active/static
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

4C - Tire Pressure Monitoring 2 (4 DTCs)

DTC	Description	Status
02214:000	Tire pressure warning	Active/static

01316:013	Brake control module - Please read DTC	Active/static
01314:004	Engine control unit - No signal/communication	Passive/Sporadic
00778:013	Steering angle sensor - Please read DTC	Active/static

52 - Passenger's door electronics (2 DTCs)

DTC	Description	Status
01333:004	Left rear door control module - No signal/communication	Passive/Sporadic
00446:000	Function limitation due to insufficient voltage	Passive/Sporadic

55 - Headlight Regulation (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
03278:000	Function limitation due to missing message	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
03278:000	Function limitation due to missing message	Passive/Sporadic

62 - Left rear door electronics (1 DTC)

DTC	Description	Status
00446:000	Function limitation due to insufficient voltage	Passive/Sporadic

69 - Trailer Function (2 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

6C - Camera System Rear View (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00778:013	Steering angle sensor - Please read DTC	Active/static

72 - Right rear door electronics (1 DTC)

DTC	Description	Status
00446:000	Function limitation due to insufficient voltage	Passive/Sporadic

Technician Notes

2016756180

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.