

**Shop: --**Tel: -Email: --

Address: --

Report ID: MAXIA20240228132109 Test Time: 2024-02-28 13:21:09

Technician: Andrick

## **Audi VEHICLE DIAGNOSTIC REPORT**

#### **Vehicle Information**

--/Audi/Audi A4/S4/RS4 USA/CAN 2009>/--

VIN: WAUZZZ8K1EA056020

**Customer Information** 

Name: MFC Dekra Nedbank Auction House

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V19.50

Odometer Reading: 257302 License Plate: CW45FNGP

Tel: 0861033572

Serial Number: VB8GJCC01509

Repair Order Number: --

# 🔁 System Scanned( 19 )

System	Status/DTC
01 - Engine Control Module 1	<b>Q</b> 10
02 - Transmission electronics	<b>Q</b> 1
03 - Brakes 1	<b>Q</b> 3
05 - Access/start authorization	<b>Q</b> 4
08 - Air Conditioning	<b>Q</b> 3
09 - Electronic central electric	<b>Q</b> 1
15 - Airbag	<b>②</b> 0
16 - Steering column electronics	<b>Q</b> 1
17 - Instrument cluster	<b>②</b> 0
19 - Gateway	<b>Q</b> 1
42 - Driver's door electronics	<b>②</b> 0
44 - Power Steering	<b>Q</b> 1
46 - Comfort System Central Control Module	<b>©</b> 6
52 - Passenger's door electronics	<b>②</b> 0
53 - Parking Brake	<b>Q</b> 2
56 - Radio	<b>Q</b> 1
62 - Left rear door electronics	<b>②</b> 0
72 - Right rear door electronics	<b>②</b> 0

MaxiSys MS906 BT

Page 1

## 77 - Telephone





## **DTC (34)**

#### 01 - Engine Control Module 1 (10 DTCs)

or Engine of	million Module 1 (10 b 103)	
DTC	Description	Status
P00B700	Engine Coolant Flow Low/Performance	Passive/Sporadic
P008900	Fuel Pressure Regulator 'A' Performance	Passive/Sporadic
P011600	Coolant temperature sensor 1 Circuit range/performance	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic
P001400	B Camshaft Position (Bank1) Timing over-advanced or System Performance	Passive/Sporadic
P219600	O2 Sensor Signal Stuck Rich Bank 1 Sensor 1	Active/static
P017100	Fuel Trim,Bank1 System too Lean	Passive/Sporadic
P000B00	'B' Camshaft Position Slow Response (Bank 1)	Passive/Sporadic
U041500	Invalid data received from ABS control unit	Active/static
P029900	Turbocharger/supercharger underboost	Passive/Sporadic
02 - Transmis	sion electronics (1 DTC)	
DTC	Description	Status
D102C00	Clutch activation implausible	Daggiya/Sparadia

DTC	Description	Status
P183C00	Clutch activation implausible	Passive/Sporadic

### 03 - Brakes 1 (3 DTCs)

DTC	Description	Status
00283:008	Left front ABS wheel speed sensor - Implausible signal	Active/static
00473:013	Electronic parking brake control module -J540 Please read DTC	Active/static
00283:012	Left front ABS wheel speed sensor - Electrical error in circuit	Active/static

### 05 - Access/start authorization (4 DTCs)

DTC	Description	Status
00955:002	Key 1 - Lower limit not reached	Active/static
00956:002	Key 2 - Lower limit not reached	Passive/Sporadic
01330:013	Comfort system central control module - Please read DTC	Active/static
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

www.autel.com

MaxiSys MS906 BT Page 2

Page 3

Audi/ Audi A4/S4/RS4 USA/CAN 2009>/	Test Time	2024-02-28 13:21:09	Report ID:	MAXIA2024022813210
Audi/ Audi A4/ 34/ 1134 03A/ CAN 2003//	Test Tille.	2024-02-20 13.21.03	neport ib.	WANIAZUZ4UZZU I JZ I U

## **Technician Notes**

2016284790

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 4