



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240108093338
Test Time: 2024-01-08 09:33:38
Technician: Werner

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3'/330d_N57/--
VIN: WBA8F36060NT48332

Odometer Reading: 156707km
License Plate: FSK108L

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.10

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(22)

System		Status/DTC
DDE (Engine-Diesel Electronics)		 6
EGS (Electronic Transmission Management)		 0
DSC (Dynamic Stability Control)		 1
ACSM (Airbag-Advanced Crash Safety Module)		 0
KOMBI (Instrument Cluster)		 1
FEM (Front Electronic Module)		 3
TRSVS (All Round View Camera)		 0
ZGM (Central Gateway Module)		 1
EKPS (Electric Fuel Pump Control)		 0
ICM (Integrated Chassis Management)		 0
EPS (Electric Power Steering)		 0
TBX (Touchbox)		 0
AMPT (Top Hi-Fi Amplifier)		 0
FLEL (Frontal Light Electronics Left)		 0
FLER (Frontal Light Electronics Right)		 0
FZD (Roof Function Center)		 1
GWS (Gear Selector Switch)		 0
TCB (Combox Emergency Call)		 0



HUH (Headunit High) ✓ 0

CON (Controller) ✓ 0

REM (Rear Electronic Module) ✓ 0

IHKA (Integrated Automatic Heating And A/C System) ✓ 0



DTC (13)

DDE (Engine-Diesel Electronics) (6 DTCs)

DTC	Description	Status
242200	Glow element, cylinder 1, activation: Glow element resistance outside specification	Permanent
242A00	Glow element, cylinder 3, activation: Glow element resistance outside specification	Permanent
242E00	Glow element, cylinder 4, activation: Glow element resistance outside specification	Permanent
288B00	Power management: Standby current violation	Intermittent
24F400	Electric fan, activation: Open circuit	Intermittent
288F00	Power management: Reduction or switching-off of individual electrical consumers	Intermittent

DSC (Dynamic Stability Control) (1 DTC)

DTC	Description	Status
480A90	DSC: Roller brake tester mode active	Intermittent

KOMBI (Instrument Cluster) (1 DTC)

DTC	Description	Status
E12C1D	Signal (afterrunning, terminal 30, fault-controlled) invalid, transmitter JBE/FEM/BDC	Intermittent

FEM (Front Electronic Module) (3 DTCs)

DTC	Description	Status
8040B9	De-activation of terminal 30B: Top startability limit reached	Intermittent
8040BD	Reset or deactivation of terminal 30F	Intermittent
8041A8	Welcome light repeat lock active	Intermittent

ZGM (Central Gateway Module) (1 DTC)

DTC	Description	Status
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent

FZD (Roof Function Center) (1 DTC)

DTC	Description	Status
-----	-------------	--------

801A55

DWA: The alarm has been activated

Permanent

Technician Notes

2016220563

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.