



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	23/09/2026		M57 Pretoria Road - 1619
Inspection Date	23/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	CHEVROLET	Registration Number	JB72WZGP
Model	UTILITY 1.4 CLUB PU [2011-2017]	Register Number	
VIN	ADMLF4MR1F4741077	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/11/2026
Color	WHITE	Power / Displacement	
Year Model	2015	Paint Finish	TWO COAT UNI
Km Reading	104,915 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:

2017302754

DATE

23/09/2026



Damage	Repair Way
Engine Oil Leak	Replace
Engine Wiring Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Right Damaged	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Interior Mirror Damaged	Replace
Sun Visor Left Damaged	Repair
Sun Visor Right Damaged	Repair
Gear Lever Dust Boot Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Broken	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Fuel Cap Damaged	Replace
Roof Damaged	Repair
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Front Right Worn	Replace
Shock Absorber Rear Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Gearbox Oil Leak	Repair
Brakes Insufficient	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.41	0.81	-	
Rear	0.1	2.62	-	
Emergency / Parking	0.27	1.33	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R14	86H	Velocity	Radial	V	1221	1 mm
Front Right	185/65R14	86H	Velocity	Radial	V	1221	0 mm
Rear Left	175/70R13	82H	Interstate	Radial	V	4509	0 mm
Rear Right	185/65R14	86H	Velocity	Radial	V	0519	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P0502:00	VEHICLE SPEED SENSOR CIRCUIT LOW VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 4 DTC'S AT TIME OF TESTING SEE DTC REPORT.Engine Compartment: Battery loose.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.
Tyres and Rims: rear tar sizes do not match.
Road Test: handbrake does not work.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:


2017302754

DATE


23/09/2026



Brake test.



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:

2017302754

DATE

23/09/2026



Rear bumper



Rear bumper



Rear Fender Left



Rear Fender Right



Front Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



Roof



Windscreen Wiper



Engine Wiring



Headlight Right



Tail Light Right



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:


2017302754

DATE

23/09/2026



Fuel Cap



Seat Front Right



Seat Front Left



Sun Visor Left



Sun Visor Right



Interior Mirror

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



Gear Lever Dust Boot



Shock Absorber Rear Left



Engine



Gearbox



Tyre Front Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077



CONDITION REPORT



Report No:
2017302754
DATE
23/09/2026



Engine Wiring



Shock Absorber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMLF4MR1F4741077