



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
GautengDEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	06/05/2025		M57 Pretoria Road - 1619
Inspection Date	06/05/2025		Kempton Park - GT


Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	HBJ289L
Model	HILUX 2.4 GD-6 SRX 4X4 D-CAB DSL PU AT [2019-2021]	Register Number	
VIN	AHTKB8CD702975246	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2025
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	198,902 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Grill Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Gearbox Oil Leak	Repair
Body exterior	Vehicle got minor scratches, stone chips and dents

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112S	Bridgestone	Dueler	V	0723	2 mm
Front Right	265/65R17	112S	Bridgestone	Dueler	V	4121	2 mm
Rear Left	265/65R17	112S	Bridgestone	Dueler	V	1423	3 mm
Rear Right	265/65R17	112S	Bridgestone	Dueler	V	1323	4 mm
Spare	265/65R17	120/117P	Nk sport	Conqueror	V	1122	7 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	P1605	ROUGH IDLING	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871


DATE
06/05/2025

VEHICLE INFORMATION			
Make/Model	Year	Engine	Color
Toyota Hilux	2018	2.8L Diesel	White
Registration	Chassis No.	Engine No.	Body No.
12345678	987654321	123456789	987654321
INSPECTION RESULTS			
Item	Pass/Fail	Remarks	Priority
Engine Oil Level	Pass	Oil level is adequate	Low
Brake Pads	Pass	Brake pads are within limits	Low
Lighting	Pass	All lights are functioning	Low
Wash/Wax	Pass	Vehicle is clean	Low
Overall Condition	Pass	Vehicle is in good condition	Low

Shock report

DIAGNOSTIC TEST RESULTS			
System	Test Result	Pass/Fail	Remarks
Engine	Idle speed 750 RPM	Pass	Idle speed is within limits
Transmission	Shift points	Pass	Shift points are correct
Brakes	Brake pressure	Pass	Brake pressure is adequate
Steering	Steering angle	Pass	Steering angle is correct
Wash/Wax	Wash/Wax	Pass	Vehicle is clean

Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246




CONDITION REPORT


Report No: 2016866871

DATE
06/05/2025


90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

Coolant bottle



Water level



Bonnet



Grill



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

Windscreen



Tailgate



Rear Fender Right



Door Rear Right



Front Fender Right



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246



CONDITION REPORT

Report No: 2016866871

DATE
06/05/2025

Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTKB8CD702975246