



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 05/03/2024 | | M57 Pretoria Road - 1619 |
| Inspection Date | 05/03/2024 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | TOYOTA | Registration Number | LK16WGGP |
| Model | QUANTUM | Register Number | |
| VIN | AHTSS22P407153001 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 4 | License Expiry Date | 30/09/2024 |
| Color | WHITE | Power / Displacement | |
| Year Model | | Paint Finish | TWO COAT UNI |
| Km Reading | 32,463 KM | Fuel | DIESEL |
| Cab / Body Type | STATION WAGON | Transmission | MANUAL |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

| Damage | Repair Way |
|-----------------------------------|---|
| Front Bumper Damaged | Repair |
| Bonnet Damaged | Repair |
| Front Fender Left Damaged | Repair |
| Rear Fender Left Damaged | Repair |
| Rear Fender Right Damaged | Repair |
| Door Front Left Damaged | Repair |
| Door Front Right Damaged | Repair |
| Door Rear Left Damaged | Repair |
| Boot Lid / Hatch door Damaged | Repair |
| Sill Panel Left Damaged | Repair |
| Sill Panel Right Welded | Repair |
| Jacking Point Front Right Damaged | Repair |
| Gearbox Mountings Damaged | Repair |
| Fuel Tank Damaged | Replace |
| Body and exterior | Minor dents and scratches and stone chips. |
| Body and exterior | Signs of repair work done to somebody panels. |
| Body and exterior | Repair work done to vehicle below-standard. |
| Body and exterior | Poor alignment to some body panels. |
| Body and exterior | signs of impact damage to right side of vehicle |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407153001



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

Brakes

Brake Test Results

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 4.49 | 5.21 | - | |
| Rear | 3.37 | 3.62 | - | |
| Emergency / Parking | 2.23 | 1.5 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|---------|------------------|-------------|--------|-------|-----------------|------------------|
| Front Left | 195R15C | 106S | Toyo | Radial | V | 2323 | 3 mm |
| Front Right | 195R15C | 106S | Toyo | Radial | V | 2323 | 3 mm |
| Rear Left | 195R15C | 106S | Toyo | Radial | V | 2323 | 3 mm |
| Rear Right | 195R15C | 106S | Toyo | Radial | V | 2323 | 3 mm |

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016293658


2 / 9

DATE


05/03/2024



Brake and shock test



Diagnostic report



Diagnostic report



Manual



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

VIN: AHTSS22P407153001

DATE

05/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

VIN: AHTSS22P407153001

5 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

VIN: AHTSS22P407153001


6 / 9




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

VIN: AHTSS22P407153001

7 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024



VIN PLATE OR STICKER



ENGINE 1

HTSS22P407153001
8 / 9



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick



Water level

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

VIN: AHTSS22P407153001

9 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658


DATE
05/03/2024



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear Fender Right



Door Front Right



Rear Fender Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016293658

DATE
05/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za