



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/07/2024		M57 Pretoria Road - 1619
Inspection Date	11/07/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	LF74ZHGP
Model	QUANTUM	Register Number	
VIN	AHTSS22P507149555	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	28/02/2025
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	84,267 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Brake Light Centre Cracked	Replace
Number Plate Light Left Defective	Replace
Number Plate Light Right Damaged	Replace
Seat Rear Damaged	Repair
Dash Padding Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Rear Fender Left / Inner Tray Welded	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Residual Traces of Repair	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake Drum 2. Axle left Defective	Repair
Parking Brake Performance Insufficient	Repair
Shock Absorber Rear Left Loose / Excessive Play	Repair
Tyre Front Left Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Main Beam Left Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507149555

1 / 17



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

Damage	Repair Way
Main Beam Right Welded	Repair
Chassis Welded	Repair
Sub Frame Dented	Repair
Engine mountings Loose / Excessive Play	Replace
Gearbox Defective	Repair
Radiator Cradle Dented	Repair
Differential Oil Sweat	Repair
Steering Malfunction	Repair
Brakes Insufficient	Repair
Engine Noise Excessive	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair
Road test	Vehicle struggles to start
Interior	Interior boot panel damaged.
Engine	Engine bay dirty
Body and Exterior	Jig marks on left and right sill panles
Tyres and rims	Front and rear hubcaps scratched
Tyres and rims	Spare wheel missing
Engine	Engine oil sump dented
Undercarriage	Left and right engine brackets missing
Undercarriage	Gearbox dust plate missing
Undercarriage	Rear right leaf spring bracket damaged
Road test	Vehicle unsafe to drive
Body and Exterior	Vehicle safety integrity compromised
Body and Exterior	Vehicle is a cut and joint
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Signs of impact damage to rear of vehicle .
Body and Exterior	Stone chips and spray work on some body panels
Body and Exterior	Some body panels misaligned
Interior	Rear left door side step damaged

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	3.8	4.68	-	
Rear	0.2	0.5	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15C	106S	Toyo	H07	V	5019	1 mm
Front Right	195R15C	106S	Bridgestone	Taxi	V	4321	3 mm
Rear Left	195R15C	106R	Windforce	Touring	V	1519	0 mm
Rear Right	195R15C	106R	Toyo	HO7	V	1423	0 mm

* Tyre Legend: V=Virgin, R=Recap



CONDITION REPORT

VIN: AHTSS22B507149555

Report No: 2016450460

2 / 17

DATE

11/07/2024

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/VSC//TRC	C1201	ENGINE/EV CONTROL SYSTEM MALFUNCTION	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase


This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT


Report No: 2016450460
VIN: AHTSS22P507149555
DATE
11/07/2024



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

VIN: AHTSS22P507149555
DATE: 11/07/2024
4 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE

11/07/2024

VIN: AHTSS22P507149555-

5 / 17



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555

6 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSC22P507149555

7 / 17



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555

8 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024




VIN PLATE OR STICKER




ENGINE 1



Front chassis



Rear chassis



Engine oil sump



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555

10 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Rear right leaf spring bracket



Rear left door side step


VIN: AHTSS22P507149555
11 / 17



Interior boot panel



Dash Padding



Sill Panel Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555
12 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Rear Fender Right



Rear bumper

VIN: AHTS622P507149555
13 / 17



Rear bumper



Brake Light Centre



C • Pillar Right



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555

14 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Rear Fender Left



Door Rear Left

VIN: AHTSS2...507149555
15 / 17



Sill Panel Left



Number Plate Light Left



Number Plate Light Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

VIN: AHTSS22P507149555

16 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Front Bumper



Bonnet

VIN: AHTSS2P507149555

17 / 17




Windscreen



Grill



Water level



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Engine




Sill Panel Right



Rear Fender Right / Inner Tray



Tyre Rear Left



Tyre Rear Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Engine



Tyre Front Left



Radiator Cradle



Sub Frame



Engine mountings



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Engine mountings



Shock Absorber Rear Left



Differential



Brake Drum 2. Axle left



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Chassis



Main Beam Right



Chassis



Rear Fender Right



Main Beam Left



Rear Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024



Rear Fender Right / Inner Tray



Seat Rear



Seat Rear



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016450460

DATE
11/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za