



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**


|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 19/02/2024        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 19/02/2024        |                     | Kempton Park - GT        |

**Vehicle Data**

|                 |                   |                         |                   |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | TOYOTA            | Registration Number     | JZ89KKGP          |
| Model           | QUANTUM           | Register Number         |                   |
| VIN             | AHTSX22P607107350 | Date Of First Licensing |                   |
| Engine Number   |                   | Last COR                |                   |
| Doors           | 4                 | License Expiry Date     | 30/09/2024        |
| Color           | WHITE             | Power / Displacement    |                   |
| Year Model      |                   | Paint Finish            | TWO COAT UNI      |
| Km Reading      | 200,721 KM        | Fuel                    | PETROL            |
| Cab / Body Type | STATION WAGON     | Transmission            | MANUAL            |

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



| Damage   | Repair Way |
|--|------------|
| Battery clamps Defective                             | Repair     |
| Radio/CD/USB Defective                               | Replace    |
| Center Console / Cubbyhole + Lid Defective           | Repair     |
| Tail Light Left Scratched                            | Repair     |
| Tail Light Right Defective                           | Replace    |
| Number Plate Light Left Defective                    | Repair     |
| Number Plate Light Right Defective                   | Repair     |
| Headlight Left Damaged                               | Replace    |
| Seat Front Right Damaged                             | Repair     |
| Seat Rear Damaged                                    | Repair     |
| Sun Visor Right Damaged                              | Repair     |
| Hood Lining Defective                                | Repair     |
| Door Sealing Rubber Rear Left Damaged                | Replace    |
| Steering Wheel Trim Defective                        | Repair     |
| Number Plate Front Dented                            | Replace    |
| Front Bumper Paintwork • Scratched                   | Repair     |
| Grill Paintwork • Scratched                          | Repair     |
| Bonnet Paintwork • Chipmarks                         | Repair     |
| Firewall Damaged                                     | Repair     |
| A • Pillar Left Damaged                              | Repair     |
| Front Fender Right Damaged                           | Repair     |
| Rear Fender Left Damaged                             | Repair     |
| Rear Fender Right Damaged                            | Repair     |
| Rear Fender Left / Inner Tray Paintwork • Scratched  | Repair     |
| Rear Fender Right / Inner Tray Paintwork • Scratched | Repair     |
| Door Front Left Paintwork • Scratched                | Repair     |
| Door Front Right Paintwork • Scratched               | Repair     |
| Door Rear Left Paintwork • Scratched                 | Repair     |
| Boot Lid / Hatch door Damaged                        | Repair     |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTSX22P607107350

1 / 17



**CONDITION REPORT**

VIN: AUTO/322607197206

Report No: 2016272986

2 / 17

DATE

19/02/2024

**Comments**

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

**Concluding Remarks**

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

**Technician**

Sibusiso Mokase

This document was created electronically and is valid without signature.

## General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




## CONDITION REPORT

Report No: 2016272986

VIN: AHTSX22P607107350

DATE

19/02/2024



Brake and shock absorber report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



## CONDITION REPORT

Report No: 2016272986

DATE

VIN: AHTSX22P6070272024

16/07/2024

4 / 17

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE

19/02/2024

VIN: AHTSX22P607107350

5 / 17



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

6 / 17

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

8 / 17

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Front chassis



Rear chassis



Spare wheel Accessories



Rear left door lock



Rear left side step



Oil cap and dipstick



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

10 / 17



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Manual Transmission



Sun Visor Right



Hood Lining



Seat Front Right



Sill Panel Right



Sill Panel Right



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

12 / 17



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Door Front Right



Rear Fender Right



Rear bumper



Rear bumper



Boot Lid / Hatch door



Tail Light Right





## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

14 / 17



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Tail Light Left



Rear Fender Left



Door Rear Left



A • Pillar Left



Door Front Left



Headlight Left



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

VIN: AHTSX22P607107350

16 / 17



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Front Fender Right



Bonnet

VIN: AHTSX2ZP607107350

17 / 17



Windscreen



Number Plate Front



Front Bumper



Front Bumper



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Grill




Water level



Water level



Firewall



Parking Brake Performance



Bolt(s) / Nut(s) Front Wheel Right



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Bolt(s) / Nut(s) Rear Wheel Right



Bolt(s) / Nut(s) Rear Wheel Left



Rocker Panel Left



Rocker Panel Right



Steering box



Radiator Cradle



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Tyre Rear Right



Spare Tyre



Steering Rack Boot Left



Steering Rack Boot Right



Fuel Tank



Stabilizer Mounting Front Left



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Battery clamps



Steering Wheel Trim



Seat Rear



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray



Door Sealing Rubber Rear Left



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

Center Console / Cubbyhole + Lid



Radio/CD/USB



Number Plate Light Left



Number Plate Light Right



Roof



## CONDITION REPORT

Report No: 2016272986

DATE  
19/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)