

JEEP VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/JEEP/JK-Wrangler/--

VIN: 1C4BJWJG2CL265719

Odometer Reading: 113057

License Plate: KD11KLGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V10.51

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned (11)

| System | Status/DTC |
|--|------------|
| ECM(Engine Control Module) | 2 |
| ABS(Anti Lock Brakes) | 1 |
| ORC(Air Bag/Occupant Restraint) | 0 |
| MIC/CCN(Mechanical Instrument Cluster) | 0 |
| CGW(Central Gateway) | 0 |
| SAS(Steering Angle Sensor) | 0 |
| RADIO(Radio) | 2 |
| HVAC(Heat, Ventilation And A/C) | 0 |
| AMP(Amplifier) | 0 |
| WCM/TPMS(Wireless Control) | 1 |
| ASBS(Automatic Sway Bar System) | 0 |

DTC (6)

ECM(Engine Control Module) (2 DTCs)

| DTC | Description | Status |
|-------|---|--------|
| P0369 | Camshaft position (CMP) sensor intermittent - bank 1 sensor 2 | Stored |
| P0344 | Camshaft position (CMP) sensor intermittent - bank 1 sensor 1 | Stored |

ABS(Anti Lock Brakes) (1 DTC)

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|

| | | |
|-------|------------------------------|--------|
| C121C | Torque request signal denied | Stored |
|-------|------------------------------|--------|

RADIO(Radio) (2 DTCs)

| DTC | Description | Status |
|-------|-----------------------------|--------|
| B142D | Audio antenna not connected | Stored |
| B210A | System voltage low | Stored |

WCM/TPMS(Wireless Control) (1 DTC)

| DTC | Description | Status |
|-------|---------------------------------|--------|
| C1502 | Tire pressure sensor 2 internal | Active |

Technician Notes

2016204425

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.