Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261022100800
Test Time: 2026-10-22 10:08:00
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6R - Polo 2010 >/--
VIN: AAVZZZ6RZEU031299

Odometer Reading: 150201
License Plate: JZV499NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	2
03 - Brakes 1	0
08 - Air conditioning	0
09 - Electronic central electric	3
15 - Airbag	2
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	2
44 - Power steering	0
56 - Radio	3

DTC (12)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
17978:000	Engine control unit disabled	Passive/Sporadic
16711:000	Knock Sensor 1 Circ. Low Input	Active/static

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
03444:008	Ignition starter switch - Implausible signal	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
B102029	Key switch for airbag shutoff on front passenger side , Range/performance	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
03138:011	Input AUX IN - Open circuit	Active/static

Technician Notes

2017315732

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.