Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261110131846
Test Time: 2026-11-10 13:18:46
Technician: Barney

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZKU019029

Odometer Reading: 217027
License Plate: JB03YWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	0
04 - Steering Angle Sender	0
09 - Electronic central electric	1
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	0
44 - Power steering	0
56 - Radio	0

DTC (1)

09 - Electronic central electric (1 DTC)

DTC	Description	Status
03591:011	Signal horn activation - Open circuit	Passive/Sporadic

Technician Notes

2017324144

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.