



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250417113247
Test Time: 2025-04-17 11:32:47
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZLU017266

Odometer Reading: 109749
License Plate: JN77JYGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --



System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	✓ 0
02 - Transmission electronics	✗ 4
03 - Brakes 1	✗ 5
04 - Steering Angle Sender	✗ 1
09 - Electronic central electric	✗ 4
15 - Airbag	✗ 1
17 - Instrument cluster	✗ 1
19 - Gateway	✗ 1
25 - Anti-Theft Immobilizer	✓ 0
44 - Power Steering	✗ 1



DTC (18)

02 - Transmission electronics (4 DTCs)

DTC	Description	Status
P070900	Transmission Range Sensor 'A' Circuit Intermittent	Passive/Sporadic
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic
U041500	Invalid data received from ABS control unit	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
-----	-------------	--------



C114602	TPMS Signal error	Active/static
U102400	Instrument cluster control unit Read DTC	Active/static
B116804	Steering angle sensor Faulty	Active/static
B116829	Steering angle sensor Range/performance	Active/static
B116804	Steering angle sensor Faulty	Passive/Sporadic

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
B116807	Steering angle sensor mechanical malfunction	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
03429:011	Activation of right cornering light - Open circuit	Active/static
03302:008	Return message regarding passenger door closing condition - Implausible signal	Active/static
00975:011	Rear window defogger - Open circuit	Active/static
03587:007	Starter lock activation - Short circuit to ground	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B10021B	Front passenger airbag igniter Resistance too high	Active/static

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B103F1B	Exterior temperature sensor Resistance too high	Active/static

19 - Gateway (1 DTC)

DTC	Description	Status
01336:004	Combination Comfort databus - No signal/communication	Active/static

44 - Power Steering (1 DTC)

DTC	Description	Status
U111300	Function limitation due to received malfunction value	Passive/Sporadic

Technician Notes

2016847492

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.