

Shop: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20240624084738 Test Time: 2024-06-24 08:47:38

Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--

VIN: AAVZZZ6RZMU005193

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V20.50

Odometer Reading: 100797 License Plate: JT77NMGP

Tel: 0861033572

Serial Number: VB8GJCC01514

Status

Repair Order Number: --

🔁 System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	◎ 0
03 - Brakes 1	Q 1
09 - Electronic central electric	Q 2
15 - Airbag	Q 2
17 - Instrument cluster	3 1
19 - Gateway	② 0
25 - Anti-Theft Immobilizer	Q 1
44 - Power Steering	Q 1
56 - Radio	◎ 5

🔼 DTC (13)

03 - Brakes 1 (1 DTC)

	2 dod. p. dod.	
U140000	Function restriction Caused by low voltage	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

Description

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC Description Status

www.autel.com

MaxiSys MS906 BT

Page 1

/Volkswagen/6RS - Polo Vivo 2018 >		t Time: 2024-06-24 08:47:38	Report ID:	MAXIA20240624084738		
U101100	Supply voltage Voltage too low		Passive/	Sporadic		
U140000	Function restriction Caused by low voltage			Passive/Sporadic		
17 - Instrumen	t cluster (1 DTC)					
DTC	Description		Status			
U101100	Supply voltage Voltage too low			Passive/Sporadic		
25 - Anti-Theft	Immobilizer (1 DTC)					
DTC	Description			Status		
B104A00	Engine control unit 1/power electronics 4 not authorized			Sporadic		
44 - Power Ste	ering (1 DTC)					
DTC	Description		Status			
U101100	Supply voltage Voltage too low		Passive/Sporadic			
56 - Radio (5 D	TCs)					
DTC	Description		Status			
00446:002	Function limitation due to insu not reached	ion limitation due to insufficient voltage - Lower limit eached		Passive/Sporadic		
00532:002	Supply voltage - Lower limit no	ower limit not reached		Passive/Sporadic		
00870:011	Left front bass speaker - Open	circuit	Active/static			
00871:011	Right front bass speaker - Oper	bass speaker - Open circuit		Active/static		
01044:000	Control module incorrectly cod	led	Passive/	Sporadic		
Technician No 2016427983	otes					
		Customer name:				

Note:Please save a copy of this report for your records.

Page 2

Technician:

Date: _____

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

