

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/Polo Vivo/--
VIN: AAVZZZ6RZMU006591

Odometer Reading: 86353
License Plate: KSB293NW

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 2
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 0
56 - Radio	 1

DTC (4)

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00975:011	Rear window defogger - Open circuit	Active/static
03591:011	Signal horn activation - Open circuit	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2016959106

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.