



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250728152936

Test Time: 2025-07-28 15:29:36

Technician: Werner

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--

VIN: AAVZZZ6RZMU016559

Odometer Reading: 83542

License Plate: FPP610L

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Version: V22.50

Serial Number: VB8GJCC01514

Repair Order Number: --

## System Scanned( 9 )

| System                           | Status/DTC |
|----------------------------------|------------|
| 01 - Engine Control Module 1     | 0          |
| 03 - Brakes 1                    | 0          |
| 09 - Electronic central electric | 0          |
| 15 - Airbag                      | 0          |
| 17 - Instrument cluster          | 0          |
| 19 - Gateway                     | 0          |
| 25 - Anti-Theft Immobilizer      | 0          |
| 44 - Power Steering              | 0          |
| 56 - Radio                       | 1          |

## DTC ( 1 )

### 56 - Radio ( 1 DTC )

| DTC       | Description                      | Status        |
|-----------|----------------------------------|---------------|
| 00856:011 | Antenna, on radio - Open circuit | Active/static |

## Technician Notes

2016960721

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

