

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/Polo Vivo/--
VIN: AAVZZZ6RZNU016072

Odometer Reading: 80462
License Plate: KR58ZLGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 1
04 - Steering Angle Sender	 0
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 0
56 - Radio	 3

 DTC (7)

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C102D00	Tire pressure warning	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
03304:008	Return message for right rear door closing condition - Implausible signal	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00870:011	Left front bass speaker - Open circuit	Active/static
00871:011	Right front bass speaker - Open circuit	Active/static
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2016958178

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.