



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250820125651  
Test Time: 2025-08-20 12:56:51  
Technician: Werner

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--  
VIN: AAVZZZ6RZPU019380

Odometer Reading: 53501  
License Plate: HBC629L

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V23.00

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 9 )

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 0
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
56 - Radio	 1

## DTC ( 1 )

### 56 - Radio ( 1 DTC )

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

## Technician Notes

2016985819

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

