



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250729125231
Test Time: 2025-07-29 12:52:31
Technician: Sbu961522

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZPU019986
Odometer Reading: 30840km
License Plate: HBD705L

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 0
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
56 - Radio	 0

DTC (0)

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

