



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241106131229
Test Time: 2024-11-06 13:12:29
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZEU021729
Odometer Reading: 284740km
License Plate: FN55CLGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V21.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	✓ 0
02 - Transmission electronics	✓ 0
03 - Brakes 1	✓ 0
09 - Electronic central electric	✗ 1
15 - Airbag	✗ 1
17 - Instrument cluster	✗ 2
19 - Gateway	✓ 0
25 - Anti-Theft Immobilizer	✓ 0
44 - Power Steering	✓ 0
46 - Comfort System Central Control Module	✗ 1

DTC (5)

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
-----	-------------	--------



01314:049	Engine control unit - No communication	Passive/Sporadic
01316:049	Brake control module - No communication	Passive/Sporadic

46 - Comfort System Central Control Module (1 DTC)

DTC	Description	Status
00849:025	S-contact at ignition starter switch - Undefined switch condition	Active/static

Technician Notes

2016601150

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.