



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250729123415
Test Time: 2025-07-29 12:34:15
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZGU019215

Odometer Reading: 155292
License Plate: LF03GKGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	 2
03 - Brakes 1	 0
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
46 - Comfort System Central Control Module	 1
56 - Radio	 1

DTC (6)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P1355:00/0-4949:000	Ignition activation cyl. 1 Open circuit	Passive/Sporadic
P1361:00/0-4961:000	Ignition activation cyl. 3 Open circuit	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)



DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

46 - Comfort System Central Control Module (1 DTC)

DTC	Description	Status
01135:036	Interior monitoring sensors - Open circuit	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
00856:036	Antenna, on radio - Open circuit	Active/static

Technician Notes

2016961534

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.