Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026114945
Test Time: 2026-10-26 11:49:45
Technician: Sbu

2017 (H) Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2017 (H)/Volkswagen/6S - Polo VIVO 2/--
VIN: AAVZZZ6SZHU010822

Odometer Reading: 207260km
License Plate: KX58YBGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	0
09 - Electronic central electric	0
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	1
44 - Power steering	0
46 - Comfort System Central Control Module	0
56 - Radio	0

DTC (1)

25 - Immobilizer (1 DTC)

DTC	Description	Status
01176:007	Key - Signal too low	Passive/Sporadic

Technician Notes

2017317187

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.