



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250728151456
Test Time: 2025-07-28 15:14:56
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZHU025429

Odometer Reading: 148229
License Plate: FBS863L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 5
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
45 - Interior Monitoring	 0
46 - Comfort System Central Control Module	 0

DTC (7)

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (5 DTCs)

DTC	Description	Status
00771:030	Fuel level sensor - Open circuit/short circuit to B+	Passive/Sporadic
01314:049	Engine control unit - No communication	Passive/Sporadic



01316:049	Brake control module - No communication	Passive/Sporadic
00457:049	Vehicle Electrical System Control Module - No communication	Passive/Sporadic
01309:049	Power steering control module - No communication	Passive/Sporadic

Technician Notes
2016960716

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.