

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZHU029355

Odometer Reading: 204302
License Plate: HC33GRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 3
03 - Brakes 1	 0
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 0
44 - Power steering	 0
46 - Comfort System Central Control Module	 0

DTC (5)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
P0073:00/00 115:000	Ambient Air Temperature Sensor Circuit High	Active/static
P0328:00/00 808:000	Knock Sensor 1 Circ. High Input	Passive/Sporadic
P0300:00/00 768:000	Random/Multiple Cylinder Misfire Detected	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
-----	-------------	--------

00532:007 Supply voltage - Signal too low

Passive/Sporadic

Technician Notes
2017304204

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.