



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250415122734
Test Time: 2025-04-15 12:27:34
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZHU033170
Odometer Reading: 155967
License Plate: FVZ841L

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	✓ 0
03 - Brakes 1	✓ 0
09 - Electronic central electric	✗ 1
15 - Airbag	✗ 1
17 - Instrument cluster	✓ 0
19 - Gateway	✓ 0
25 - Anti-Theft Immobilizer	✓ 0
44 - Power Steering	✗ 2
46 - Comfort System Central Control Module	✗ 2
56 - Radio	✗ 1

DTC (7)

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

44 - Power Steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic



U101100	Supply voltage Voltage too low	Passive/Sporadic
---------	-----------------------------------	------------------

46 - Comfort System Central Control Module (2 DTCs)

DTC	Description	Status
01330:053	Comfort system central control module - Voltage supply too low	Passive/Sporadic
01135:036	Interior monitoring sensors - Open circuit	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01044:026	Control module incorrectly coded - Output open	Active/static

Technician Notes
2016843982

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.