

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZJU000830

Odometer Reading: 154112km
License Plate: KWG997MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 2
03 - Brakes 1	 4
08 - Air conditioning	 0
09 - Electronic central electric	 11
15 - Airbag	 1
17 - Instrument cluster	 1
19 - Gateway	 0
44 - Power steering	 3
5F - Information electronics 1	 5

DTC (27)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
U101700	ABS Control Module Check event memory	Active/static
U043100	Invalid data received from body control module A	Passive/Sporadic

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
U101400	Control module incorrectly coded	Active/static
C114602	TPMS Signal error	Active/static
C102D00	Tire pressure warning	Active/static
C101B14	Right front ABS Wheel Speed Sensor (WSS) Circuit open or short to ground	Active/static

09 - Electronic central electric (11 DTCs)

DTC	Description	Status
B121D15	Left DRL bulb Circuit open or short to positive	Passive/Sporadic
B12E915	Right side marker lamp bulb Open circuit/short circuit to B+	Passive/Sporadic
B133A15	Left brake/tail lamp bulb Open circuit/short circuit to B+	Active/static
B18FBF0	Terminal 75 Limp home mode active	Active/static
B168001	Front passenger central locking lock unit Electrical error	Passive/Sporadic
B168029	Front passenger central locking lock unit Range/performance	Active/static
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
B131529	Driver side window regulator control unit Range/performance	Active/static
B14D254	Window regulator front passenger side No basic setting	Passive/Sporadic
U120F00	Window regulator motor, front passenger side No communication	Passive/Sporadic
U121000	Front passenger side window regulator motor Message implausible	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U112300	Databus error value received	Active/static

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B104C29	Key Range/performance	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
U112300	Databus error value received	Active/static
U101400	Control module incorrectly coded	Active/static
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (5 DTCs)

DTC	Description	Status
-----	-------------	--------

U101100	Supply voltage Voltage too low	Passive/Sporadic
B201A00	Check online function	Active/static
B106213	Right front bass speaker Open circuit	Active/static
B105F13	Left front bass speaker Open circuit	Active/static
B106513	Left rear bass speaker Open circuit	Active/static

Technician Notes
2017303151

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.