

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZJU067233

Odometer Reading: 26622km
License Plate: KB38RTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	 11
03 - Brakes 1	 1
08 - Air conditioning	 3
09 - Electronic central electric	 9
15 - Airbag	 3
17 - Instrument cluster	 5
19 - Gateway	 2
3C - Lane change assistance	 2
44 - Power steering	 3
5F - Information electronics 1	 3
76 - Parking aid	 13
CA - Sunroof control module	 7

DTC (62)

01 - Engine Control Module 1 (11 DTCs)

DTC	Description	Status
P019700	Oil temperature sensor Short circuit to ground	Passive/Sporadic
P227900	Intake air system leakage	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U102500	Climate Control Module Check event memory	Active/static

P029900	Turbocharger/supercharger underboost	Active/static
P055600	Brake booster pressure sensor circuit range/performance	Active/static
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014800	Fuel Delivery Error	Passive/Sporadic
P125000	Fuel level too low	Active/static
P334B00	Charge air pressure actuator Mechanical fault	Active/static
P334B00	Charge air pressure actuator Mechanical fault	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C102D00	Tire pressure warning	Active/static

08 - Air conditioning (3 DTCs)

DTC	Description	Status
B109211	Recirculation flap motor Circuit short to ground	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
B10AE31	High pressure sensor No signal	Active/static

09 - Electronic central electric (9 DTCs)

DTC	Description	Status
B11EA15	Right front turn signal bulb open circuit/short circuit to B+	Active/static
B121815	Right low beam headlamp bulb Circuit open or short to positive	Active/static
B121A15	Right high beam headlamp bulb Open circuit/short circuit to B+	Active/static
B121E15	Right DRL bulb Circuit open or short to positive	Active/static
B12E915	Right side marker lamp bulb Open circuit/short circuit to B+	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system Voltage supply below lower limit	Passive/Sporadic

B131D04	Sirens/alarm horn for anti-theft warning system Faulty	Passive/Sporadic
B14D154	Front window regulator, driver side No basic setting	Active/static

15 - Airbag (3 DTCs)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
B201C00	Supply voltage Range/performance	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

17 - Instrument cluster (5 DTCs)

DTC	Description	Status
B200041	Ctrl. module faulty	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Passive/Sporadic

3C - Lane change assistance (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

U140000	Function restriction due to low voltage	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B106213	Right front bass speaker Open circuit	Active/static
B129B13	Microphone 1 Open circuit	Passive/Sporadic

76 - Parking aid (13 DTCs)

DTC	Description	Status
B10F614	Left front side parking aid sensor Circuit open or short to ground	Active/static
B10F714	Left front park assist sensor Open circuit/short circuit to ground	Active/static
B10F731	Left front parking aid sensor No signal	Passive/Sporadic
B10F812	Left front center parking aid sensor Circuit short to positive	Passive/Sporadic
B10F814	Left front center parking aid sensor Circuit open or short to ground	Active/static
B10F831	Left front center parking aid sensor No signal	Passive/Sporadic
B10F914	Right front center parking aid sensor Open circuit/short circuit to ground (GND)	Passive/Sporadic
B10FA14	Right front park assist sensor Open circuit/short circuit to ground	Active/static
B10FB14	Right front side parking aid sensor Circuit open or short to ground	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

CA - Sunroof control module (7 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B154354	Sunroof No basic setting	Active/static
B133F12	Background lighting for switch (terminal 58xt) Circuit short to positive	Passive/Sporadic
B169400	no vehicle coded	Active/static
U112100	Data bus message missing	Active/static
U112200	Data bus message implausible	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

Technician Notes
2017305036

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.