

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZKU101382

Odometer Reading: 283795km
License Plate: LF95JWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 1
03 - Brakes 1	 2
08 - Air conditioning	 1
09 - Electronic central electric	 2
15 - Airbag	 0
17 - Instrument cluster	 1
19 - Gateway	 2
44 - Power steering	 2
5F - Information electronics 1	 1

DTC (12)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
U101700	ABS Control Module Check event memory	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
C102D00	Tire pressure warning	Active/static

08 - Air conditioning (1 DTC)

DTC	Description	Status
B109211	Recirculation flap motor Circuit short to ground	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B121D15	Left DRL bulb Circuit open or short to positive	Passive/Sporadic
B147918	Remote control vehicle key 1 Insufficient current	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B104B31	Key No signal	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B106513	Left rear bass speaker Open circuit	Active/static

Technician Notes
2017304915

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.