

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZKU109439

Odometer Reading: 82046km
License Plate: LN23VFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 1
03 - Brakes 1	 0
08 - Air conditioning	 0
09 - Electronic central electric	 3
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
44 - Power steering	 1
5F - Information electronics 1	 1

DTC (6)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P15A100	Transmission gear N sensor Signal implausible	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
B121815	Right low beam headlamp bulb Circuit open or short to positive	Passive/Sporadic
B121E15	Right DRL bulb Circuit open or short to positive	Active/static
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B129B13	Microphone 1 Open circuit	Passive/Sporadic

Technician Notes
2017302501

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.