Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZMU066823

Odometer Reading: 152494km
License Plate: FWT238L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
01 - Engine Control Module 1	15
03 - Brakes 1	0
08 - Air conditioning	0
09 - Electronic central electric	14
13 - Adaptive cruise control ADAS	4
15 - Airbag	1
17 - Instrument cluster	3
19 - Gateway	1
3C - Lane change assistance ADAS	1
44 - Power steering	1
5F - Information electronics 1	6
76 - Parking aid ADAS	1
CA - Sunroof control module	0

DTC (47)

01 - Engine Control Module 1 (15 DTCs)

DTC	Description	Status
P051200	Starter Request Circuit	Passive/Sporadic
P06E900	Engine Starter Performance	Active/static
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U044300	Invalid data received from body control module B	Active/static

P218500	Coolant temperature sensor 2 circuit high	Active/static
P086B00	Neutral Position Sensor 'A' Range/Performance	Passive/Sporadic
U140A00	Terminal 30 ,Open circuit	Passive/Sporadic
P210600	Throttle Actuator Control System ,Forced Limited Power	Passive/Sporadic
P154500	Throttle valve control system ,Malfunction	Passive/Sporadic
P014C00	O2 Sensor Bank 1 Sensor 1 ,Slow Response - Rich to Lean	Passive/Sporadic
P052100	Engine oil pressure sensor/switch A ,Range/performance	Passive/Sporadic
P010600	Manifold absolute pressure/barometric pressure , Range/performance	Passive/Sporadic
P010800	Manifold absolute pressure/barometric pressure ,High input	Passive/Sporadic
P007D00	Charge Air Cooler Temperature Sensor Circuit High ,Bank 1	Passive/Sporadic

09 - Electronic central electric (14 DTCs)

DTC	Description	Status
B121715	Left low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B121815	Right low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B121D15	Left DRL bulb ,Circuit open or short to positive	Active/static
B121F15	Left fog lamp bulb ,Circuit open or short to positive	Active/static
B122015	Right fog lamp bulb ,Circuit open or short to positive	Active/static
B12E815	Left side marker lamp bulb ,Open circuit/short circuit to B+	Passive/Sporadic
B133A15	Left brake/tail lamp bulb ,Open circuit/short circuit to B+	Active/static
B133C15	Right brake/tail lamp bulb ,Open circuit/short circuit to B+	Active/static
B131FF5	Driver side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B1320F5	Passenger side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B132054	Passenger side rear window regulator ,No basic setting	Passive/Sporadic
B14D1F5	Front driver window regulator ,Supply voltage below lower limit	Passive/Sporadic
B14D2F5	Front passenger window regulator ,Supply voltage below lower limit	Passive/Sporadic
B14D254	Window regulator front passenger side ,No basic setting	Passive/Sporadic

13 - Adaptive cruise control (4 DTCs)

DTC	Description	Status

U112300	Databus error value received	Active/static
B200FF0	Internal malfunction	Passive/Sporadic
C110BF0	Automatic distance control sensor ,Limited visibility	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U111000	Function restriction due to communication interruption	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic

3C - Lane change assistance (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (6 DTCs)

DTC	Description	Status
B106513	Left rear bass speaker ,Open circuit	Active/static
B106713	Right rear bass speaker ,Open circuit	Active/static
B110231	Rearview camera ,No signal	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U111000	Function restriction due to communication interruption	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

76 - Parking aid (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

Technician Notes

2017316347

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.