# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZMU102370

Odometer Reading: 186760km
License Plate: KD12NNGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 11 )

| System | Status/DTC |
|---|---|
| 01 - Engine Control Module 1 | 6 |
| 02 - Transmission electronics | 1 |
| 03 - Brakes 1 | 0 |
| 08 - Air conditioning | 0 |
| 09 - Electronic central electric | 0 |
| 15 - Airbag | 0 |
| 17 - Instrument cluster | 3 |
| 19 - Gateway | 0 |
| 44 - Power steering | 1 |
| 5F - Information electronics 1 | 0 |
| CA - Sunroof control module | 0 |

## DTC ( 11 )

### 01 - Engine Control Module 1 ( 6 DTCs )

| DTC | Description | Status |
|---|---|---|
| P013A00 | O2 Sensor Slow Response - Rich to Lean Bank 1 Sensor 2 | Passive/Sporadic |
| P030000 | Random Misfire Detected ,No Sub Type Information | Passive/Sporadic |
| P030100 | Cylinder 1 Misfire Detected ,No Sub Type Information | Passive/Sporadic |
| P030200 | Cylinder 2 Misfire Detected ,No Sub Type Information | Passive/Sporadic |
| P030300 | Cylinder 3 Misfire Detected ,No Sub Type Information | Passive/Sporadic |
| P130A00 | Cylinder suppression | Passive/Sporadic |

### 02 - Transmission electronics ( 1 DTC )

| DTC | Description | Status |
|---|---|---|

| | | |
|---|---|---|
| P177B00 | Clutch 1 ,Tolerance limit reached | Passive/Sporadic |

## 17 - Instrument cluster ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|
| U111000 | Function restriction due to communication interruption | Passive/Sporadic |
| B104B31 | Key ,No signal | Passive/Sporadic |
| B104C29 | Key ,Range/performance | Passive/Sporadic |

## 44 - Power steering ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| B200FF0 | Internal malfunction | Passive/Sporadic |

## Technician Notes

2017316044

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*