

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZPU030506

Odometer Reading: 103202km
License Plate: KX94ZYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
08 - Air conditioning	 0
09 - Electronic central electric	 0
15 - Airbag	 0
17 - Instrument cluster	 1
19 - Gateway	 2
44 - Power steering	 1
5F - Information electronics 1	 0

DTC (4)

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U111000	Function restriction due to communication interruption	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U140600	Static current too high	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

Technician Notes

2017304622

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.