



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260923113055
Test Time: 2026-09-23 11:30:55
Technician: Werner

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVBRRAR1L4106322

Odometer Reading: 125017
License Plate: FYL431L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.61

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (1)

System	Status/DTC
SCD(Speedometer Control Device)	0



DTC (0)

Technician Notes

2017302469

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.