



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250619151605
Test Time: 2025-06-19 15:16:05
Technician: Sbu

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVMRRAR1J4045222
Odometer Reading: 187322
License Plate: KBD980MP


Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.43
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(1)

System	Status/DTC
SCD(Speedometer Control Device)	 0

DTC (0)

Technician Notes

2016918298

Customer name: _____
Technician: _____
Date: _____

Note:Please save a copy of this report for your records.

