

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVRRCHR4K4071632

Odometer Reading: 266995
License Plate: KD08KCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.70

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (4)

System	Status/DTC
ECM(Engine Control Module)	✓ 0
ABS(Anti-lock Brake System)	✗ 2
IMMO(Immobilizer)	✓ 0
SCD(Speedometer Control Device)	✓ 0



DTC (2)

ABS(Anti-lock Brake System) (2 DTCs)

DTC	Description	Status
C0800_07	High voltage	Not present
C0161_00	Brake switch circuit fault (ABS/ESC)	Not present

Technician Notes

2017304542

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.