



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250627105310
Test Time: 2025-06-27 10:53:10
Technician: Travino

Chevrolet VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chevrolet/Optra/--
VIN: ADMCF80HEC4589523

Odometer Reading: 169420
License Plate: NO reg n

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V29.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(2)

System	Status/DTC
Engine control module	 0
Electronic brake control module	 4

DTC (4)

Electronic brake control module (4 DTCs)

DTC	Description	Status
		DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Requested
C0035:00	Left front wheel speed sensor circuit	
		DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Requested
C0040:00	Right front wheel speed sensor circuit	



C0161:00 ABS brake pedal position sensor circuit

DTC history status :
History
Since DTC clear : Passed
Last test : Failed current
DTC
This ignition cycle :
Passed
MIL status : Requested

C0236:71 Engine speed signal for traction control system circuit
invalid data

DTC history status :
History
Since DTC clear : Passed
Last test : Passed
This ignition cycle :
Passed
MIL status : Not requested

Technician Notes
2016927175

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.