



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250507135227  
Test Time: 2025-05-07 13:52:27  
Technician: Andrick

# Chevrolet VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Chevrolet/Utility/--  
VIN: ADMCF80HED4613130

Odometer Reading: 282339  
License Plate: JYM007MP

## Customer Information

Name: Dekra MFC AUCTION HOUSE



Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V28.10

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 2 )

System	Status/DTC
Engine control module	 2
Electronic brake control module	 2

## DTC ( 4 )

### Engine control module ( 2 DTCs )

DTC	Description	Status
P0036:00	Heated oxygen sensor heater control circuit sensor 2	DTC history status : Not history Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested
P0138:00	Heated oxygen sensor circuit high voltage sensor 2	DTC history status : Not history Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Passed and failed MIL status : Not requested

### Electronic brake control module ( 2 DTCs )

DTC	Description	Status
-----	-------------	--------



C0161:00	Antilock braking system brake switch circuit malfunction	DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Requested
C0800:03	Control module power circuit low voltage	DTC history status : History Since DTC clear : Passed Last test : Passed This ignition cycle : Passed MIL status : Not requested

Technician Notes  
2016868717

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.