Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026133432
Test Time: 2026-10-26 13:34:32
Technician: Sbu

Chevrolet VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chevrolet/Utility/--
VIN: ADMJF4MR6H4787532

Odometer Reading: 244020
License Plate: KNW143MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V34.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
Engine control module	0
Electronic brake control module	0

DTC (0)

Technician Notes

2017317285

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.