

# Nissan VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Nissan/NP 300/--  
VIN: ADNAPGD22ZR124396

Odometer Reading: 186093  
License Plate: KG16CBGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V10.71

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 4 )

| System  | Status/DTC                                                                            |
|---------|---------------------------------------------------------------------------------------|
| Engine  |  1 |
| ABS     |  2 |
| Air bag |  0 |
| BCM     |  1 |

## DTC ( 4 )

### Engine ( 1 DTC )

| DTC   | Description | Status  |
|-------|-------------|---------|
| P0089 | Fuel pump   | Current |

### ABS ( 2 DTCs )

| DTC   | Description          | Status  |
|-------|----------------------|---------|
| C1103 | Right front sensor 1 | Current |
| C1107 | Right front sensor 2 | Current |

### BCM ( 1 DTC )

| DTC   | Description               | Status |
|-------|---------------------------|--------|
| U1000 | CAN communication circuit | Past   |

## Technician Notes

2017305283

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.