



Shop: Dekra MFC
 Tel: 0861033572
 Email: --
 Address: MFC Auction House
 M57 Pretoria Road
 Glen Marais
 Kempton Park
 1619

Report ID: MAXIA20231129133503
 Test Time: 2023-11-29 13:35:03
 Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP 300/--

VIN: ADNCPGD22ZR115185

Odometer Reading: 210096

License Plate: FBR024L

Customer Information

Name: MFC MFC

Tel: 0000

Device information

Scanner: MaxiSys MS906 BT

Version: V9.50

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(4)

System	Status/DTC
Engine	2
ABS	0
Air bag	0
BCM	1

DTC (3)

Engine (2 DTCs)

DTC	Description	Status
P0183	Fuel temp SEN/CIRC	Current
P0103	MAF SEN/CIRCUIT	Current

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2016183465

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.