Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261019122459
Test Time: 2026-10-19 12:24:59
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Tiida/--
VIN: ADNFCAC11Z2030162

Odometer Reading: 133595
License Plate: KH40GRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
Engine	2
Air bag	2

DTC (4)

Engine (2 DTCs)

DTC	Description	Status
P1610	Lock mode	Past
P1615	Difference of key	2 Time

Air bag (2 DTCs)

DTC	Description	Status
B1035	Crash zone sensor	Past
B1033	Crash zone sensor	Past

Technician Notes

2017314581

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.