Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261009131342
Test Time: 2026-10-09 13:13:42
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0036983

Odometer Reading: 105547
License Plate: BP96HSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
BCM	4

DTC (4)

BCM (4 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
002002	Please refer to vehicle service manual.	
2A0500	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2017310484

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.