

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0145117

Odometer Reading: 232591
License Plate: LLV585MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
BCM	 5

DTC (5)

BCM (5 DTCs)

DTC	Description	Status
040000	Please refer to vehicle service manual.	
000100	Please refer to vehicle service manual.	
042002	Please refer to vehicle service manual.	
000400	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2017305034

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.