

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0167511

Odometer Reading: 57520
License Plate: NO reg

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
Air bag	 1

DTC (1)

Air bag (1 DTC)

DTC	Description	Status
B1042	ECU supply voltage	Past

Technician Notes

2017299407

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.