



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250728130015
Test Time: 2025-07-28 13:00:15
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0180163

Odometer Reading: 86538
License Plate: BK47VKZN

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(2)

System	Status/DTC
Air bag	 1
BCM	 2

DTC (3)

Air bag (1 DTC)

DTC	Description	Status
B1042	ECU supply voltage	Past

BCM (2 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2016960583

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

